

- 1 (BSP October 13, 2003)
- 2 Steel angles connecting the timber blockout to the existing steel truss
- 3 members shall conform to either ASTM A 36M or ASTM A 992M, and
- 4 shall be galvanized in accordance with AASHTO M 111.